



Challenges faced at Gold Loan & Currency Chest Branches

Security	Installation & maintenance	Incidents
Inefficient and unreliable security guards	Managing Installations /Maintenance PAN India with many vendors	Delay in getting video of critical incidents
High and ever-increasing cost of Security	Timely identification of faulty surveillance equipment	Problems due to non-availability of incident videos
Managing compliance of Security guards	Un-scheduled replacement costs of faulty equipment	Inability to view sites LIVE from anywhere
Day-time Hold-Up		
Storming of vaults		
Burglary break-In by tunnelling		
Break-in through adjacent wall		
Vault door kept open		

SAVE UP TO 60% OF YOUR SECURITY COSTS



Standard & Enhanced Security:

ACTIDETER®	Secures Branches against Intrusion using Video Verification, Lights and Sound
ACTIDETER® ENHANCED SECURITY	Provides additional security to Gold Loan and Currency Chest Branches
High Level Securiy:	
ACTIOTP®	OTP based on LIVE view of Vault and branch area
ACTIINTERLOCK [™]	High Security access to Gold Loan branches
ACTISMOKE [™]	Instant Smoke on detecting on-going Vault Robbery
ACTISHUTTER®	Electronic closing of shutter in case of hold-up
ACTILIVE	LIVE view of Vault are for unmatched security
Other Value-Added Solutio	ns:
ACTICARE [®]	Alerts on failure of any surveillance equipment along with Comprehensive AMC

<u>ACTIMOBILE</u>[™]

Alerts on failure of any surveillance equipment along with Comprehensive AM Provides additional security to Gold Loan and Currency Chest Branches

To know more, check out

https://www.securens.in/sectors/security-solution-for-gold-loan-currency-chest-branches/



22,000 Sites 50+ Customers 450+ Employees

99% Detection & Deterrence rate

National & International Award-Winning Monitoring Center

Image: Start floor, B-Wing, Greenscape Technocity, Opp. Millennium Business Park, Mahape, Navi Mumbai - 400 701.

Image: start s